

























# COUNCIL AGENDA ITEM # \_\_\_\_ FOR TUESDAY, JUNE 22<sup>ND</sup>, 2004

CITY CLEEK DEPARTMENT 2007 JUN 17 NM 9 18

### **BUILDING PERMITS AND INSPECTIONS**

# MEMORANDUM June 14, 2004

TO:

The Honorable Mayor and City Council

THROUGH: R. Alan Shubert, P. E. - Building Permits and Inspections Director

FROM:

Tom Maguire, Housing Compliance Supervisor

SUBJECT:

11661 Norman Montion Drive

(Rep. District #5)

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated February 25<sup>th</sup>, 2004. The building was found to be in an advanced state of disrepair. The building has been used as a harborage by unwanted persons.
- 2) A certified condemnation letter was mailed to Ida M. Poole, 11661 Norman Montion Drive, El Paso, Texas 79936, on March 16<sup>th</sup>, 2004.
- 3) Certified notices of the public hearing scheduled June 22<sup>nd</sup>, 2004 were mailed to the owners and all interested parties on June 1<sup>st</sup>, 2004.
- 4) As of May 4<sup>th</sup>, 2004, \$9,401.72 are owed in taxes.
- 5) There has been no response from the owner.

# The Department recommends that it be found:

- 1) That the main structure and accessory building be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the buildings are not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structure's certificate of occupancy be revoked; and
- 4) That the structure can be repaired; and
- 5) That the main and accessory structures be demolished within 30 days; and
- 6) That the premises be cleaned of all weeds, trash, and debris within 30 days.



# **UNSAFE STRUCTURES REPORT**

# **BUILDING PERMITS AND INSPECTIONS**

**DATE OF EXAMINATION: 2/25/04** 

**REP. DISTRICT:** 5

ADDRESS: 11661 Norman Montion Drive

ZONED: R-3A

LEGAL DESCRIPTION: Lot 43, Block 66, Vista Hills Unit #20

OWNER: Ida M. Poole

ADDRESS: 11661 Norman Montion Drive

**BUILDING USE:** Abandoned single family home

TYPE OF CONSTRUCTION: III

FOOTINGS: Reinforced concrete

**CONDITION:** Fair. No indication of structural failure.

FOUNDATION WALL: N/A

CONDITION:

FLOOR STRUCTURE: Reinforced concrete slab on grade.

CONDITION: Fair.

**EXTERIOR WALLS:** Stucco & brick

HEIGHT: 18'

THICKNESS: 8"

CONDITION: Fair.

INTERIOR WALLS & CEILINGS: 2 x 4 wood frame, sheetrock

CONDITION: Very poor. Numerous sections of sheetrock have been vandalized and would have

to be replaced.

**ROOF STRUCTURE:** Wood sheathing, asphalt shingles **CONDITION:** Fair. Some areas of roof need to be resealed.

DOORS, WINDOWS, ETC.: Aluminum slide windows, wood doors

**CONDITION:** Very poor. Windows have been broken and doors damaged from vandalization and would have to be replaced.

**MEANS OF EGRESS: N/A** 

CONDITION:

**PLUMBING:** Water is off. A licensed plumber should be hired to evaluate system and bring up to code.

**ELECTRICAL:** Electricity if off. A licensed electrician should be hired to evaluate system and bring up to code.

**MECHANICAL:** Very poor. Parts of mechanical system are missing. A licensed mechanical contractor should be hired to evaluate system and bring up to code.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: 0

WARNING POSTED: No

BARRICADED: No

POLICE AID REQD.: No

**REMARKS:** The general structure of the building is fair. Serious damage to interior by vandalization needs to be addressed. We recommend the structure be secured until repairs are made.

Timothy H. Grabe

**Building Inspector** 

JOE WARDY MAYOR



BUILDING PERMITS AND INSPECTIONS CODE COMPLIANCE March 9, 2004

Ida M. Poole 11661 Norman Montion Dr. El Paso, Texas 79936-0712

## CITY COUNCIL

SUSAN AUSTIN DISTRICT NO. 1

ROBERT A. CUSHING Jr. DISTRICT NO. 2

JOSE ALEXANDRO LOZANO DISTRICT NO. 3

> JOHN COOK DISTRICT NO. 4

DANIEL S. POWER DISTRICT NO. 5

PAUL J. ESCOBAR DISTRICT NO. 6

Re: 11661 Norman Montion Dr.

Lot: 43

Blk: 66, Vista Hills Unit 20

Zoned: R-3A COD04-0261

Certified Mail Receipt # 7003 1680 0000 1712 0961

VIVIAN ROJAS DISTRICT NO. 7

ANTHONY COBOS
DISTRICT NO. 8

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.52.030 - Unsafe Structures - Owner Not To Allow Condition To Continue, which states:

It is unlawful for the owner of any building or structure, or part thereof, which has become unsafe and dangerous so as to endanger persons or property, or so as to be a fire hazard by reason of defective construction, overloaded floors, lack of guards against fire, defective condition of the foundations, walls, or parts thereof, or deterioration caused by fire or otherwise, or for any reason, to allow or permit same to remain upon any real estate within the City.

The El Paso Municipal Code Chapter 18.52.040 - unsafe structures - Remedial action by owner or City defines unsafe structure as a structure or part thereof that is:

- a. Dilapidated, substandard, or unfit for human habitation and a hazard to the public health, safety, and welfare; or
- b. Regardless of its structural condition, unoccupied by its owners, lessees or other invitees and is unsecured from unauthorized entry to the extent that it could be entered or used by vagrants or other uninvited persons as a place of harborage or could be entered or used by children; or

## 11661 Norman Montion Drive

- c. Boarded up, fenced, or otherwise secured in any manner in if:
- i. The building constitutes a danger to the public even though secured entry, or
- ii. The means used to secure the building are inadequate to prevent unauthorized entry or use of the building in the manner described by subsection.

The structure located at 11661 Norman Montion Drive has the following violations:

- a. The floors have not been maintained in a safe manner.
- b. The walls have not been maintained in a safe manner free of holes and cracks.
- c. The roof structure has not been maintained free of defects that may cause leaks.
- d. The plumbing system is inadequate and does not meet minimum code requirements.
- e. The electrical system is inadequate and does not meet minimum code requirements.
- f. The HVAC system is inadequate and does not meet minimum code requirements.
- g. The structure is open and accessible to unauthorized entry.
- h. The premises are full of weeds, trash, and debris.
- i. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter.
- j. In the event you fail to correct these violations within 30 days, the case will be submitted to the City Attorney's Office for unsafe structures proceedings. The City Council will decide if the structure is unsafe and if it should be vacated, secured, repaired or demolished as per Sec. 18.52,040.

#### 11661 Norman Montion Drive

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.


According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Housing Compliance Office of the Building Permits and Inspections, 5<sup>th</sup> floor, City Hall, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 54l-4800.

FOR THE DIRECTOR FOR BUILDING PERMITS AND INSPECTIONS:

Timothy H. Grabe Building Inspector

THG/rl





HAR IN SETER 702-199

14PO 5171 0000 0841 E007

THE PROPERTY FERRISTED

Ida M. Poole 11661 Norman Montion Dr. El Paso, Texas 79936-0712

POOL661 759362007 1503 07 03/12/04
RETURN TO SENDER

POOLE MOVED LEFT NO ADDRESS UNABLE TO FORWARD RETURN TO SENDER

79936407920A41136

The section of the se	1960	U 5 FOSIA SE VICE  DEFICE D WATE RECIERT.  Demendar Out of the control of the con			
	1712				
-	۲٦	Postage \$ TG			
		Certified Fee  Return Reclept Fee (Endorsement Required)  Postmark Here			
!	1680	Restricted Delivery Fee (Endorsement Required)  Ida M. Poole			
ľ	Ida M. I dolo				
*	7003	El Paso, Texas 79936-0712			
ľ	•	a Re: 11661 Norman Monon Dr.			
5		<u></u>			
		es com deun um e code de 1945 al 1965 a sus sur como se de la minima. En contenta sur propertir de la como de la co			

大学 1000 1000 1000 1000 1000 1000 1000 10	ent desegnes, morageness to t
1960 2772 0000 D8.	2. Article Number Consolin Service (abel)
4. Restricted Delivery? (Extra Fee)	
Schrifted Mall   Express Mail   Express Mail   Express Mail   Selbrathandise   G.O.O.D.   Ismediate   Express Mail   G.O.O.D.   Ismediate   Express Mail   G.O.O.D.   Ismediate   Express Mail   Express	
3. Service Type	Re: 11661 Norman Motion Dr.
A proposal design of the proposal design of t	H Paso, Texas 79936-0712
	11661 Norman Montion Dr.
n principal de la companya de la co La companya de la co La companya de la co	ida M. Poole
D. Is delivery address different from Item 1?   If YES, enter delivery address below:   If YES, enter delivery address below:	9:of bessenbb Addressed 10:
B. Received by (Printed Name) C. Date of Delivery	so that we can return the card to you.    • Attach this card to the back of the mailplece,   or on the front if space permits.
enutengis: A  thegA   X	■ Complete Items 1; 2, and 3. Also complete items 1; 2, and 3. Also complete item 4 if Restricted Delivery is desired. ■ Print your name and address on the reverse
сомьгете тніз зестіом ом регімену	seupen: complete this section:

THE BLACK OF THE ACT OF THE PROPERTY OF THE PROPERTY AS A

Activity 8640 Desc. Refer to Rine specificing these Date Referred 3/11/2004 Date Remarked 3/11/2004 Date Completed 51	Updated: 3/11/2004 STC  Hold Level: No hold    Celerular Tag   FDCM     Report Tag     Assigned To   903     Done By     X-Cdordinate:     Y-Cdordinate:	Date Z   Section 1   Section 2   Section 2
Freeze Case M200  Responsible Dept.		ONE THO Hoid all permits and in-

